

BELPLAS USED GRANULATORS - OVER 20 IN STOCK

"BEFORE"

Cumberland 1624 machine.
In decent shape but in need of repairs, new blades, new screen, upgraded electrical to meet On. Hydro.



"AFTER"



New Blades Installed



New Screen Installed



Pulley Assembly Inspected and Adjusted. New Belts Installed



Machine Cleaned and Painted



Machines are inspected by On. Hydro and then a full test is performed using customer supplied material

QUALITY USED EQUIPMENT
Division

